

STANDARD MESSBEREICHE FÜR THERMOMETER NACH DIN STANDARD

MEASURING RANGES FOR THERMOMETER ACC. DIN

Bimetall-Thermometer

Bimetallic-thermometers

-50 °C - + 50°C
-30 °C - + 50°C
-20 °C - + 60°C
-20 °C - + 80°C
 0 - + 60°C
 0 - + 80°C
 0 - + 100°C
 0 - + 120°C
 0 - + 160°C
 0 - + 200°C
 0 - + 250°C
 0 - + 300°C
 0 - + 400°C
 0 - + 500°C

Gasgefüllte Thermometer

Gas-filled thermometers

-80 °C - + 40°C
-60 °C - + 40°C
-40 °C - + 40°C
-30 °C - + 30°C
-30 °C - + 50°C
 0 - + 60°C
 0 - + 100°C
 0 - + 120°C
 0 - + 160°C
 0 - + 200°C
 0 - + 250°C
 0 - + 300°C
 0 - + 400°C
 0 - + 500°C
 0 - + 600°C
 0 - + 800°C

Maschinen-Glasthermometer

Machinery Thermometer

-60°C - + 40°C
-30°C - + 50°C
 0 - + 100°C
 0 - + 160°C
 0 - + 200°C
 0 - + 300°C
 0 - + 400°C
 0 - + 500°C
 0 - + 600°C